









10054889-012502




10054839.012502



10054889.012502  
205210.6884501




205210 68845001






10054889.012502

### 4.3. Coated Ethisorb® Patch

unfolds after insertion into endoscopic  
equipment






10054889.012502



10054889-012502



205210 6384500T 10054889 012502





Fig. 7







Fig. 8

1. High grade stainless steel  
discharge volume: 110 ml



2. Plastic  
discharge volume: 96 ml





Fig. 9

10054289-012502


10054889-012502




**FIG. 10**

Process (continued)


Added material



↓




↓



IPC: weight of dried collagen sponge blocks

↓



IPC: weight of collagen sponge strips

↓




FIG. 11